

REPORT

GENERAL INFORMATION

Report Name

Renault Midlum

Read out date

2025-07-14 13:45:57

Date of editing

2025-07-14 13:45:57

Serial number

10373 PROFESSIONAL

Unit of measure

µm

VEHICLE DATA

Type	TRUCK
Make	Renault
Model	Midlum
Engine capacity [ccm]	-
Power [kW]	-
VIN	-
Fuel Type	-
Year of production	-


COMMENT

-


MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range


PAS: general interpretation, body




LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
left front fender/ bumper	Fe	74	82	78	82	74	-	-	-	-	-
left front door	Fe+Zn	74	162	104	122	95	93	162	75	74	-
left rear door	Fe+Zn	93	131	107	107	131	98	118	97	93	-



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
right front fender/ bumper	Fe+Zn	93	104	98	104	93	-	-	-	-	-
right front door	Fe+Zn	79	149	98	85	94	149	79	85	93	-
right rear door	Fe+Zn	97	136	110	97	109	100	107	136	114	-




TOP											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
hood/bonnet	-	-	-	-	-	-	-	-	-	-	-



BACK											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
trunk/boot	Fe+Zn	92	128	104	128	115	110	92	92	92	100

Legend

- Disabled
- Paint layer is too thin
- Paint layer is original
- Second layer of paint
- A thin layer of putty
- A thick layer of putty



SYMMETRIC MEASUREMENTS

EXTERNAL MEASUREMENTS														
left front fender/ bumper	1. 82	2. 74	-	-	-	-	-	-	-	-	-	-	-	-
right front fender/ bumper	2. 93	1. 104	-	-	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	11	30												
left front door	1. 122	2. 95	3. 93	4. 162	5. 75	6. 74	-	-	-	-	-	-	-	-
right front door	6. 93	5. 85	4. 79	3. 149	2. 94	1. 85	-	-	-	-	-	-	-	-
DIFFERENCE	29	10	14	13	19	11								
left rear door	1. 107	2. 131	3. 98	4. 118	5. 97	6. 93	-	-	-	-	-	-	-	-
right rear door	6. 114	5. 136	4. 107	3. 100	2. 109	1. 97	-	-	-	-	-	-	-	-
DIFFERENCE	7	5	9	18	12	4								