

REPORT

GENERAL INFORMATION

Report Name

Kia

Read out date

2025-06-10 10:25:57

Date of editing

2025-06-10 10:40:32

Serial number

10373 PROFESSIONAL

Unit of measure

µm


VEHICLE DATA

Type	ESTATE
Make	Kia
Model	Ceed
Engine capacity [ccm]	1591
Power [kW]	93,8
VIN	U5YH5816BPL155671
Fuel Type	Gas
Year of production	2023


MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range


PAS: general interpretation, body




LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
left front fender/ bumper	Fe+Zn	54	87	70	54	56	87	85	-	-	-
left front door	Fe	68	96	80	96	91	73	82	74	77	68
left rear door	Fe	52	117	81	94	89	117	81	78	56	52
left pillar	Fe	67	103	79	74	73	67	103	-	-	-
left rear fender/ bumper	Fe	57	81	71	81	57	71	75	-	-	-



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
right front fender/ bumper	Fe	76	116	93	98	83	76	116	-	-	-
right front door	Fe+Zn	79	94	86	81	94	79	85	85	86	94
right rear door	Fe+Zn	66	104	84	69	69	81	66	97	104	99
right pillar	Fe	46	96	63	96	59	46	51	-	-	-
right rear fender/ bumper	Fe+Zn	72	102	87	72	102	76	98	-	-	-



TOP											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
hood/bonnet	Fe	65	100	87	80	65	100	100	88	-	-
roof	Fe	59	76	65	60	76	65	65	59	-	-




BACK											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
trunk/boot	Fe	52	75	62	52	52	64	75	66	-	-

Legend

- Disabled
- Paint layer is too thin
- Paint layer is original
- Second layer of paint
- A thin layer of putty
- A thick layer of putty

EXTERNAL MEASUREMENTS



SYMMETRIC MEASUREMENTS

EXTERNAL MEASUREMENTS														
left front fender/ bumper	1. 54	2. 56	3. 87	4. 85	-	-	-	-	-	-	-	-	-	-
right front fender/ bumper	4. 116	3. 76	2. 83	1. 98	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	62	20	4	13										
left front door	1. 96	2. 91	3. 73	4. 82	5. 74	6. 77	7. 68	-	-	-	-	-	-	-
right front door	7. 94	6. 86	5. 85	4. 85	3. 79	2. 94	1. 81	-	-	-	-	-	-	-
DIFFERENCE	2	5	12	3	5	17	13							
left rear door	1. 94	2. 89	3. 117	4. 81	5. 78	6. 56	7. 52	-	-	-	-	-	-	-
right rear door	7. 99	6. 104	5. 97	4. 66	3. 81	2. 69	1. 69	-	-	-	-	-	-	-
DIFFERENCE	5	15	20	15	3	13	17							
left pillar	1. 74	2. 73	3. 67	4. 103	-	-	-	-	-	-	-	-	-	-
right pillar	4. 51	3. 46	2. 59	1. 96	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	23	27	8	7										
left rear fender/ bumper	1. 81	2. 57	3. 71	4. 75	-	-	-	-	-	-	-	-	-	-
right rear fender/ bumper	4. 98	3. 76	2. 102	1. 72	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	17	19	31	3										