

REPORT

GENERAL INFORMATION

Report Name

Skoda kidiaq

Read out date

2025-04-14 10:24:53

Date of editing

2025-04-14 12:31:45

Serial number

10373 PROFESSIONAL

Unit of measure

µm


VEHICLE DATA

Type	SUV
Make	Skoda
Model	Kodiaq
Engine capacity [ccm]	-
Power [kW]	-
VIN	TMBLK7NS1K8073435
Fuel Type	-
Year of production	-


MEASUREMENTS

"-" means measurement skip, "∞" means measurement out of range


PAS: general interpretation, body




LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
left front fender/bumper	Fe+Zn	88	117	103	101	117	105	88	-	-	-
left front door	Fe+Zn	108	122	117	121	108	116	119	122	-	-
left rear door	Fe	85	123	112	117	123	116	120	85	-	-
left pillar	Fe+Zn	91	133	110	133	91	102	115	-	-	-
left rear fender/bumper	Fe+Zn	117	138	129	117	138	120	136	133	-	-



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
right front fender/bumper	Fe	82	110	100	82	103	105	110	-	-	-
right front door	Fe+Zn	103	126	115	120	121	104	103	126	-	-
right rear door	Fe+Zn	82	125	107	82	114	108	106	125	-	-
right pillar	Fe	90	116	104	114	95	90	116	-	-	-
right rear fender/bumper	Fe+Zn	95	128	112	95	114	101	128	122	-	-




TOP											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
hood/bonnet	Fe+Zn	88	124	104	99	88	124	111	98	-	-
roof	Fe+Zn	121	141	131	128	138	126	121	141	-	-



BACK											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
trunk/boot	Fe+Zn	116	127	123	127	116	127	-	-	-	-

Legend

- Disabled
- Paint layer is too thin
- Paint layer is original
- Second layer of paint
- A thin layer of putty
- A thick layer of putty



SYMMETRIC MEASUREMENTS

EXTERNAL MEASUREMENTS														
left front fender/ bumper	1. 101	2. 117	3. 105	4. 88	-	-	-	-	-	-	-	-	-	-
right front fender/ bumper	4. 110	3. 105	2. 103	1. 82	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	9	12	2	6										
left front door	1. 121	2. 108	3. 116	4. 119	5. 122	-	-	-	-	-	-	-	-	-
right front door	5. 126	4. 103	3. 104	2. 121	1. 120	-	-	-	-	-	-	-	-	-
DIFFERENCE	5	5	12	2	2									
left rear door	1. 117	2. 123	3. 116	4. 120	5. 85	-	-	-	-	-	-	-	-	-
right rear door	5. 125	4. 106	3. 108	2. 114	1. 82	-	-	-	-	-	-	-	-	-
DIFFERENCE	8	17	8	6	3									
left pillar	1. 133	2. 91	3. 102	4. 115	-	-	-	-	-	-	-	-	-	-
right pillar	4. 116	3. 90	2. 95	1. 114	-	-	-	-	-	-	-	-	-	-
DIFFERENCE	17	1	7	1										
left rear fender/ bumper	1. 117	2. 138	3. 120	4. 136	5. 133	-	-	-	-	-	-	-	-	-
right rear fender/ bumper	5. 122	4. 128	3. 101	2. 114	1. 95	-	-	-	-	-	-	-	-	-
DIFFERENCE	5	10	19	22	38									